



Flying Tiger 10 M International Class Association

[Home](#) | [Boat](#) | [Fleets](#) | [Members](#) | [Racing](#) | [Class Association](#) | [Resources](#) | [Classifieds](#) | [Forum](#) | [Pictures](#) | [Links](#)

[Log on](#) | [Profile](#) | [Join Class Association](#) | [Renew Membership](#) | [Member List](#) | [Sail Tag List](#) | [Owner's Tools](#) | [Admin](#)

Welcome cazzaranda

[Log Out](#)

Forgot your
[username/password?](#)

From: "Don at Hiptrader" <don@hiptrader.com>
To: FT10 Owners
Subject: FT10 possible defective turn buckle body
Date: Mon, 31 Mar 2008 21:26:54 -0700

To all FT10 Owners,

We have been notified by Alexander-Roberts, U.S. Distributor and supplier of the turnbuckles, that there may be some defective turnbuckles on the FT 10.

Please check carefully your turnbuckles and look for the "punch mark" (photo attached).

If your turnbuckles do not have this mark please contact Alexander Roberts directly to arrange for replacements. All replacements will be handled directly by Alexander-Roberts Co.

Alexander-Roberts Co.

1851 Langley Ave.
Irvine, CA 92614
(949) 250-4571
att: Nick or Kathy
e-mail arcol851@sbcglobal.net

Regards,

Hiptrader, LLC

